



ALL HANDS ON DECK
EUROPEAN WORK HERITAGE IN SHIPWRIGHT FOR PRESENT AND FUTURE

(2019-1-ES01-KA204-065201)

Test Module 9
Safety at work

ALL HANDS ON DECK
European work heritage in shipwright for present and future

TEST FOR THE MODULE 9



Co-funded by the
Erasmus+ Programme
of the European Union



QUESTIONS & ANSWERS

1) How is it calculated risk rating?

- A. Impact - Use collective measures
- B. Probability of occurrence x Severity of consequences
- C. Probability of occurrence / Use collective measures + Use Personal Protective equipment (PPE)

2) Which one of the following ones is one of the most common risks in shipwright?

- A. Entrapment in machinery
- B. Fire
- C. Both answers are correct

3) Select the CORRECT sentence

- A. It is better to focus the priority on measures related with collectively protection over individual measures
- B. It is better to focus the priority on measures related with individual measures over collectively protection
- C. It makes no difference whether we take collectively protection or individual measures.

4) Use of local exhaust ventilation is considered a

- A. Individual protective equipment
- B. Collective measure
- C. Risk





5) Which one of the following sentences about safeguards on machinery in shipwright job position is FALSE

- A. It should not be easy to inactivate them
- B. They can be moved if necessary to work more quickly
- C. One of their main objectives is to retain projections

6) Which one of the following machines is considered one of the most dangerous?

- A. Thickness machine
- B. Band saw
- C. Spindle moulder

7) It is necessary to reduce the risk of working in extreme

- A. Heat
- B. Cold
- C. Both are correct

8) ¿What is a travel-lift?

- A. It is a specialised type of crane used for lifting boats out of the water and transporting them around shipyard
- B. It is used predominantly for lifting, lowering and steering pallets from one place to another.
- This is a machine with manual feed of the workpiece, equipped with a circular saw blade which is fixed during the cutting operation



9) One of the first steps to prepare the measures to avoid the risk of exposition with harmful or toxic substances is

- A. Try to buy as much as possible from the beginning to transport and storage on one occasion only
- B. Prepare an inventory of hazardous substances and in which task would be involved
- C. Personally check whether substances are safe

10) Select the CORRECT answer

- A. In shipwright job position you never work with toxic substances
- B. It is not necessary to use personal protective equipment in any case
- C. Hazardous chemicals should be labelled and give essential information

11) (insert the test of the question)?

- A.
- B.
- C.

12) (insert the test of the question)?

- A.
- B.
- C.

13) (insert the test of the question)?





A.

B.

C.

14) (insert the test of the question)?

A.

B.

C.

15) (insert the test of the question)?

A.

B.

C.

16) (insert the test of the question)?

A.

B.

C.

17) (insert the test of the question)?

A.

B.

C.

18) (insert the test of the question)?





A.

B.

C.

19) (insert the test of the question)?

A.

B.

C.

20) (insert the test of the question)?

A.

B.

C.





ALL HANDS ON DECK
EUROPEAN WORK HERITAGE IN SHIPWRIGHT FOR PRESENT AND FUTURE

(2019-1-ES01-KA204-065201)

PROJECT CONSORTIUM



This publication reflects the views only of the author, and the Commission cannot be held responsible for any use which may be made of the information contained herein.